

Chartered Surveyors and Property Consultants



Front elevation 2018



Front elevation upon completion



Poor condition of stone



Stone replacement



West elevation 2018



West elevation upon completion



Chartered Surveyors and Property Consultants



Common stair 2018



Decoration of common stair



External grounds 2018



New balustrade, slabs and decoration



New stone cornice



Build-up of gable chimney



 ${\tt Chartered\ Surveyors\ and\ Property\ Consultants}$ 



Stone replacement to front elevation



New stone chimney



New stone wallhead chimney



Stone plaque with year of restoration

